



Customer Information Bulletin

Subject: Launch of printer firmware 1.0.4-1.

Figure 4® Modular

Issue:

Firmware 1.0.4-1 has been launched. This firmware change will allow the printer to accept a new type of material pump when a replacement is needed.



Solution:



CAUTION: ONLY DOWNLOAD THIS FIRMWARE UPDATE IF YOU HAVE THE NEWEST PUMP (ABOVE, RIGHT).

If you do not already have the new pump, contact 3D Systems Service to determine your needs.

If you do have the new pump, 3D Systems Service should have given you the new firmware file, as well as a procedure to install the pump and the firmware. Also, the new pump will require a new Material Changeover (MCO) Kit. The new MCO procedure can be found in the [updated User Guide](#).

