

Customer Information Bulletin



ProX SLS 6100
CIB# CIB00077_Rev_A
Date: **June 2018**

Subject: Sinter v6.2.514

Known Issues and Resolutions:

- When build is paused, Est. Time Left and Est. Completion Time is incorrect
- Randomly the Build completion popup is not displayed and Build Report csv file will not generate
- After any Alarm on Sinter you should close Sinter and restart DSP

Product Register Trademark Disclaimer

DISCLAIMER OF LIABILITY: The following supersedes any related provision in your company's forms, letters, and agreements from, by or with 3D Systems Inc. 3D Systems Inc. makes no warranty, whether expressed or implied, including warranties of merchantability or of fitness for a particular purpose for this product. No statements or recommendations contained in the product literature are to be construed as inducements to infringe any relevant patent now or hereafter in existence. Under no circumstances shall 3D Systems Inc. be liable for incidental, consequential, special, or other damages from alleged negligence, breach of warranty, strict liability or any other theory, arising out of the manufacture, use, sale, or handling of this product. In no event shall the liability of 3D Systems Corporation for any claims arising out of the manufacture, use, handling, or sale of its products exceed an amount equal to the buyer's purchase price.

© Copyright 2018 by 3D Systems, Inc. All rights reserved. Subject to change without notice. **All ProX SLS printers and the 3D logo are registered trademarks of 3D Systems.**