


3D Professional Printers Technical Information Bulletin



3DSYSTEMS®

Reference
 Advisory
 Upgrade / Repair / Retrofit
 Safety Alert

Purpose: Retrofit for iPro/ProX Chamber Lamp Filters

- | | | | |
|----------------------------------|--|--------------------------------|--|
| <input type="checkbox"/> General | <input checked="" type="checkbox"/> iP8K | <input type="checkbox"/> Viper | <input checked="" type="checkbox"/> ProX 800 |
| <input type="checkbox"/> PJ6K | <input type="checkbox"/> iP9K | <input type="checkbox"/> 7000 | <input checked="" type="checkbox"/> ProX 950 |
| <input type="checkbox"/> PJ7K | <input type="checkbox"/> iPXL | <input type="checkbox"/> 5000 | |

The following serial number iPro 8000's, ProX 950's, and ProX 800's are known to have faulty filters on the chamber lamp assemblies. The filters currently installed will not block the UV correctly and will cause unnecessary curing in the resin. All of the following serial numbers will need QTY 2 of 286535-00 ordered to replace the filters that are currently installed in the chamber lamps. *****PLEASE RETURN THE OLD FILTERS TO TECH SUPPORT IN ROCK HILL*****

iPro8000				ProX950	ProX800	
10162202001	10162202008	10162202015	10162211804	10502202001	10602204901	10602209702
10162202002	10162202009	10162202016	10162211805	10502202002	10602209701	10602209703
10162202003	10162202010	10162202017	10162211806	10502202003	10602209702	10602209704
10162202004	10162202011	10162202018	10162211807		10602209701	10602209705
10162202005	10162202012	10162211801	10162211808			
10162202006	10162202013	10162211802	10162211809			
10162202007	10162202014	10162211803	10162211810			