

Customer Information Bulletin



CIB00224, Rev A
Date: 5/24/2021

Subject: Launch of 3D Sprint 3.1.

Figure 4® Standalone

Issue:

3D Sprint 3.1 will be coming out in the first week of June 2021! With the upgrade, your Figure 4 Standalone will now be required to run at least firmware 1.1.1.

Also, Figure 4 Standalone will now have advanced features for stacked printing.

Solution:

Firmware 1.1.2

1. If you have not upgraded to firmware 1.1.1 or 1.1.2, follow the User Guide instructions to do so here: <http://infocenter.3dsystems.com/figure4standalone/user-guide/operation/touch-screen-overview/settings-tab/firmware-updates/update-printer-firmware>
2. Only the latest version of the printer firmware, 1.1.2, is available on Infocenter. Use the Update Installer to upgrade your printer to this version.
3. Once you have upgraded to this firmware version, you will install future firmware updates through the update feature in 3D Sprint.

Stacked Printing

Industrial Stacked Printing is a semi-automated workflow to create, stack, support and print multiple copies of a single part. Please visit [Figure 4 Standalone Best Practices](#) and the [3D Sprint User Guide](#) for complete information.