



Keyboard and Mouse/Trackball Shortcuts

Press and hold these keys...	...then perform one of these actions			
	Left or right arrow	Up or down arrow	Click	Click and drag
Right button on pointing device				Dragging with the right button depressed rotates the Workspace
Ctrl	Move selected parts		Select several parts or extrusion surfaces	
Shift	Move the viewpoint			Draw a rectangle and select parts within it
Alt				Draw a rectangle and zoom in on that area.
Alt + Ctrl	Move the viewpoint	Zoom in/out	Cycle through parts under the pointer, selecting one at a time	
Alt + Shift	Rotate viewpoint in the XY plane	Rotate viewpoint in the ZY plane		Rotate the viewpoint
Ctrl + Shift	Rotate parts in the XY or XZ plane	Move parts vertically		Move the viewpoint